

Message

---

**From:** Pavitt, John [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=31D144BE2F8043A2B6DE245E1706134A-PAVITT, JOHN]  
**Sent:** 10/30/2019 6:58:34 PM  
**To:** Mallinger, Hunter L (DEC) [hunter.mallinger@alaska.gov]  
**Subject:** RE: EPA Air Compliance Inspection Report, Hilcorp Alaska LLC, MPU

I'm calling now

Sincerely,

John Pavitt, Air Compliance Inspector  
Air and Toxics Enforcement Section  
U.S. EPA Region 10  
Alaska Operations Office  
Anchorage, AK  
Phone: (907) 271-3688

---

**From:** Mallinger, Hunter L (DEC) <hunter.mallinger@alaska.gov>  
**Sent:** Wednesday, October 30, 2019 10:54 AM  
**To:** Pavitt, John <Pavitt.John@epa.gov>  
**Subject:** RE: EPA Air Compliance Inspection Report, Hilcorp Alaska LLC, MPU

Apologies: **Ex. 6 Personal Privacy (PP)**

---

**From:** Mallinger, Hunter L (DEC)  
**Sent:** Wednesday, October 30, 2019 10:53 AM  
**To:** Pavitt, John <Pavitt.John@epa.gov>  
**Subject:** RE: EPA Air Compliance Inspection Report, Hilcorp Alaska LLC, MPU

Good morning John,

I am in a conference room here in Juneau for the OOOOa Hilcorp briefing. The call-in is **Ex. 6 Personal Privacy (PP)**

Thanks!

---

**From:** Pavitt, John [mailto:Pavitt.John@epa.gov]  
**Sent:** Tuesday, October 29, 2019 2:29 PM  
**To:** jupotter@hilcorp.com  
**Cc:** McClintock, Katie <McClintock.Katie@epa.gov>; Williams, Christopher <Williams.Christopher@epa.gov>; Olds, Jason R (DEC) <jason.olds@alaska.gov>; Howard, Breanna K (DEC) <breanna.howard@alaska.gov>; Mallinger, Hunter L (DEC) <hunter.mallinger@alaska.gov>  
**Subject:** EPA Air Compliance Inspection Report, Hilcorp Alaska LLC, MPU



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
REGION 10

1200 Sixth Avenue, Suite 155  
Seattle, Washington 98101-3188

ENFORCEMENT &  
COMPLIANCE ASSURANCE  
DIVISION

Julieanna Potter (Orczewska)  
Environmental Specialist – Air Quality  
Hilcorp Alaska, LLC

Re: Clean Air Act Compliance Evaluation Inspection at the Hilcorp Alaska, LLC, Milne Point Unit, AK

Dear Ms. Potter:

On July 17, 2019, the United States Environmental Protection Agency (EPA) conducted a compliance inspection at your facility along with the Alaska Department of Environmental Conservation (ADEC). The purpose of the inspection was to determine compliance with the Clean Air Act (CAA), specifically, with New Source Performance Standards (NSPS), Subpart OOOOa – Standards of Performance for Crude Oil and Natural Gas Facilities. A copy of the inspection report is attached to this email. Please review the inspection report, note the areas of concern, and take any actions necessary to ensure compliance with the CAA.

An EPA Compliance Officer will use this inspection report in evaluating your facility's compliance with the CAA. This may result in subsequent contact from EPA personnel if a violation is identified. This message is sent only to transmit the inspection report, and it should not be interpreted as a final compliance determination. Please direct any questions regarding the compliance evaluation to me at [pavitt.john@epa.gov](mailto:pavitt.john@epa.gov).

Thank you for the cooperation and assistance extended to EPA and State personnel during the inspection.

Sincerely,

John Pavitt, Air Compliance Inspector  
Air and Toxics Enforcement Section  
U.S. EPA Region 10  
Alaska Operations Office  
Anchorage, AK  
Phone: (907) 271-3688

Attachments:

1. Inspection Report

